



**C & I LEASING PLC**  
Francaise for Nigeria

LEASING HOUSE, C & I Leasing Drive, Off Bisola Durosinmi Etti Drive, Off Admiralty Way, Lekki Ph 1, Lagos, Nigeria  
+234(0)1 2703700-5, (0)7028185019, (0)7029021757; call centre: (0)70000HERTZ  
+234(0)1 2703706  
hertz@c-leasing.com

### Fleet Maintenance Requisitions Report

| # | Branch Office | Vehicle Id | Company                       | Workshop                                     | Complaint                                                               | Maint Status        | Estimated Cost | Approved Cost |
|---|---------------|------------|-------------------------------|----------------------------------------------|-------------------------------------------------------------------------|---------------------|----------------|---------------|
| 1 | benin         | SMK 834 FR | huawei technologies (nig) ltd | olusola ajayi automobile engineering company | Routine Service and Check exhaust leakage                               | requisition created | 22,000.00      | 18,500.00     |
| 2 | lagos hq      | AAA 357 XX | pz cussions                   | olusola ajayi automobile engineering company | CARRY OUT 38,000KM ROUTINE SERVICE FUEL LEVEL 1/2 TANK                  | requisition created | 20,000.00      | 19,500.00     |
| 3 | benin         | KJA 281 XY | huawei technologies (nig) ltd | olusola ajayi automobile engineering company | Routine service @ 83,527km, check brake and check noise from front legs | requisition created | 32,500.00      | 28,500.00     |
| 4 | benin         | KJA 281 XY | huawei technologies (nig) ltd | olusola ajayi automobile engineering company | Faulty kick stater                                                      | requisition created | 3,500.00       | 3,500.00      |
| 5 | benin         | APP 67 XM  | huawei technologies (nig) ltd | olusola ajayi automobile engineering company | Routine service, Check faulty horn, A.C not cooling                     | requisition created | 31,000.00      | 26,500.00     |
| 6 | abuja         | LSR 61 XQ  | huawei technologies (nig) ltd | olusola ajayi automobile engineering company | Routine service in Akure                                                | requisition created | 13,500.00      | 11,500.00     |
| 7 | lagos hq      | BDJ 204 YL | huawei technologies (nig) ltd | olusola ajayi automobile engineering company | Carry Out Routine Service, Propeller Oil seal, two Front Hob.           | requisition created | 58,500.00      | 49,500.00     |
| 8 | benin         | APP 67 XM  | huawei technologies (nig) ltd | olusola ajayi automobile engineering company | Check steering knuckle                                                  | requisition created | 11,000.00      | 9,500.00      |
|   |               |            |                               |                                              |                                                                         | <b>Total</b>        | 192,000.00     | 167,000.00    |

**Prepared By:** Olugbohungbe Ade

**Approved By:** \_\_\_\_\_